

SRF Consulting Group, Inc.

One Carlson Parkway, Suite 150
Plymouth, MN 55447-4443

SRF No. 8060: Hwy 5
Location: Hwy 101/ 78th St
Weekday Count
SRF Consulting

File Name : 130_Hwy 101 & 78th St
Site Code : 09281120
Start Date : 2/13/2013
Page No : 1

Groups Printed- Cars+ - Heavy Vehicles

Start Time	Hwy 101 Southbound					78th St Westbound					Hwy 101 Northbound					78th St Eastbound					Int. Total
	Peds	Left	Thru	Right	App. Total	Peds	Left	Thru	Right	App. Total	Peds	Left	Thru	Right	App. Total	Peds	Left	Thru	Right	App. Total	
06:00 AM	2	0	19	4	25	0	0	2	0	2	0	1	8	3	12	1	10	1	7	19	58
06:15 AM	0	1	18	13	32	0	1	1	0	2	0	2	11	1	14	1	11	6	11	29	77
06:30 AM	1	1	16	18	36	0	1	0	1	2	0	4	10	4	18	0	19	4	16	39	95
06:45 AM	2	1	48	18	69	0	0	0	1	1	0	5	36	8	49	0	26	10	24	60	179
Total	5	3	101	53	162	0	2	3	2	7	0	12	65	16	93	2	66	21	58	147	409
07:00 AM	0	1	34	22	57	0	2	3	1	6	0	8	30	11	49	0	38	4	25	67	179
07:15 AM	1	2	48	30	81	0	0	0	0	0	0	9	48	8	65	0	49	5	22	76	222
07:30 AM	0	3	55	36	94	0	0	0	0	0	0	14	49	12	75	0	35	6	27	68	237
07:45 AM	1	6	86	28	121	0	1	1	0	2	0	14	55	17	86	0	51	16	34	101	310
Total	2	12	223	116	353	0	3	4	1	8	0	45	182	48	275	0	173	31	108	312	948
08:00 AM	1	2	60	41	104	0	0	1	0	1	0	31	48	11	90	0	48	6	27	81	276
08:15 AM	0	2	67	32	101	0	1	0	0	1	1	28	60	5	94	0	38	5	41	84	280
08:30 AM	1	2	55	28	86	0	1	0	1	2	0	16	27	9	52	0	39	4	20	63	203
08:45 AM	1	2	67	31	101	0	0	0	0	0	0	9	31	12	52	0	23	7	11	41	194
Total	3	8	249	132	392	0	2	1	1	4	1	84	166	37	288	0	148	22	99	269	953
09:00 AM	0	1	34	30	65	0	2	2	2	6	0	6	28	12	46	0	16	7	15	38	155
09:15 AM	1	5	43	31	80	0	5	2	0	7	0	6	33	11	50	0	20	4	11	35	172
*** BREAK ***																					
Total	1	6	77	61	145	0	7	4	2	13	0	12	61	23	96	0	36	11	26	73	327
*** BREAK ***																					
10:30 AM	0	1	28	24	53	0	6	2	2	10	0	10	28	16	54	0	29	4	8	41	158
10:45 AM	0	2	28	32	62	0	11	3	1	15	0	10	20	15	45	0	25	10	11	46	168
Total	0	3	56	56	115	0	17	5	3	25	0	20	48	31	99	0	54	14	19	87	326
11:00 AM	0	1	26	37	64	0	10	10	4	24	0	16	33	12	61	0	31	6	15	52	201
11:15 AM	0	1	35	29	65	0	17	10	2	29	0	14	34	16	64	0	38	9	10	57	215
11:30 AM	0	2	20	23	45	0	10	27	4	41	0	16	31	20	67	0	32	20	11	63	216
11:45 AM	0	1	43	38	82	0	17	15	3	35	0	17	40	21	78	0	30	18	11	59	254
Total	0	5	124	127	256	0	54	62	13	129	0	63	138	69	270	0	131	53	47	231	886
12:00 PM	0	3	21	28	52	0	14	24	4	42	0	15	33	20	68	0	38	23	5	66	228
12:15 PM	0	2	33	33	68	0	18	13	7	38	0	17	27	23	67	0	37	17	20	74	247
12:30 PM	0	6	29	35	70	0	14	12	2	28	0	16	41	20	77	0	36	26	19	81	256
12:45 PM	0	3	39	33	75	0	17	17	4	38	0	18	28	27	73	0	34	26	12	72	258
Total	0	14	122	129	265	0	63	66	17	146	0	66	129	90	285	0	145	92	56	293	989
01:00 PM	0	4	32	40	76	0	18	13	1	32	0	22	31	21	74	0	27	14	10	51	233
01:15 PM	0	3	34	31	68	0	11	13	1	25	0	17	43	21	81	1	34	13	9	57	231
*** BREAK ***																					
Total	0	7	66	71	144	0	29	26	2	57	0	39	74	42	155	1	61	27	19	108	464
*** BREAK ***																					
02:30 PM	0	3	37	41	81	0	29	13	3	45	0	11	33	22	66	0	34	10	13	57	249
02:45 PM	0	4	46	45	95	0	18	13	5	36	0	21	40	21	82	0	42	13	14	69	282
Total	0	7	83	86	176	0	47	26	8	81	0	32	73	43	148	0	76	23	27	126	531
03:00 PM	0	4	45	50	99	0	18	13	5	36	0	27	30	18	75	0	41	9	9	59	269
03:15 PM	0	4	43	57	104	0	20	16	6	42	0	33	43	21	97	0	66	5	20	91	334
03:30 PM	0	4	56	40	100	0	18	8	2	28	0	29	62	16	107	0	50	17	29	96	331
03:45 PM	0	3	53	79	135	0	16	11	7	34	0	29	45	21	95	0	43	14	10	67	331
Total	0	15	197	226	438	0	72	48	20	140	0	118	180	76	374	0	200	45	68	313	1265
04:00 PM	0	2	52	53	107	0	20	15	2	37	0	20	65	16	101	0	54	17	13	84	329
04:15 PM	0	3	62	62	127	0	21	14	0	35	0	21	58	21	100	0	68	13	13	94	356

SRF Consulting Group, Inc.

One Carlson Parkway, Suite 150
Plymouth, MN 55447-4443

SRF No. 8060: Hwy 5
Location: Hwy 101/ 78th St
Weekday Count
SRF Consulting


File Name : 130_Hwy 101 & 78th St
Site Code : 09281120
Start Date : 2/13/2013
Page No : 2

Groups Printed- Cars+ - Heavy Vehicles

Start Time	Hwy 101 Southbound					78th St Westbound					Hwy 101 Northbound					78th St Eastbound					Int. Total
	Peds	Left	Thru	Right	App. Total	Peds	Left	Thru	Right	App. Total	Peds	Left	Thru	Right	App. Total	Peds	Left	Thru	Right	App. Total	
04:30 PM	0	3	61	56	120	0	22	17	7	46	0	27	56	28	111	0	50	10	17	77	354
04:45 PM	0	4	55	62	121	0	20	13	9	42	0	25	68	16	109	0	64	12	13	89	361
Total	0	12	230	233	475	0	83	59	18	160	0	93	247	81	421	0	236	52	56	344	1400
05:00 PM	0	6	65	78	149	0	27	22	5	54	0	29	73	15	117	0	57	6	11	74	394
05:15 PM	0	1	71	75	147	0	22	6	8	36	0	22	81	14	117	0	70	11	7	88	388
05:30 PM	0	1	64	50	115	0	15	5	7	27	0	13	68	13	94	0	51	10	18	79	315
05:45 PM	0	2	68	49	119	0	11	10	4	25	0	24	51	16	91	0	72	4	9	85	320
Total	0	10	268	252	530	0	75	43	24	142	0	88	273	58	419	0	250	31	45	326	1417

*** BREAK ***

Grand Total	11	102	1796	1542	3451	0	454	347	111	912	1	672	1636	614	2923	3	1576	422	628	2629	9915
Apprch %	0.3	3	52	44.7		0	49.8	38	12.2		0	23	56	21		0.1	59.9	16.1	23.9		
Total %	0.1	1	18.1	15.6	34.8	0	4.6	3.5	1.1	9.2	0	6.8	16.5	6.2	29.5	0	15.9	4.3	6.3	26.5	
Cars+	9	100	1764	1517	3390	0	439	343	106	888	1	658	1604	598	2861	2	1552	416	625	2595	9734
% Cars+	81.8	98	98.2	98.4	98.2	0	96.7	98.8	95.5	97.4	100	97.9	98	97.4	97.9	66.7	98.5	98.6	99.5	98.7	98.2
Heavy Vehicles	2	2	32	25	61	0	15	4	5	24	0	14	32	16	62	1	24	6	3	34	181
% Heavy Vehicles	18.2	2	1.8	1.6	1.8	0	3.3	1.2	4.5	2.6	0	2.1	2	2.6	2.1	33.3	1.5	1.4	0.5	1.3	1.8




SRF Consulting Group, Inc.

One Carlson Parkway, Suite 150
Plymouth, MN 55447-4443

SRF No. 8060: Hwy 5
Location: Hwy 101/ 78th St
Weekday Count
SRF Consulting

File Name : 130_Hwy 101 & 78th St
Site Code : 09281120
Start Date : 2/13/2013
Page No : 3

Start Time	Hwy 101 Southbound					78th St Westbound					Hwy 101 Northbound					78th St Eastbound					Int. Total
	Peds	Left	Thru	Right	App. Total	Peds	Left	Thru	Right	App. Total	Peds	Left	Thru	Right	App. Total	Peds	Left	Thru	Right	App. Total	
Peak Hour Analysis From 06:00 AM to 08:45 AM - Peak 1 of 1																					
Peak Hour for Entire Intersection Begins at 07:30 AM																					
07:30 AM	0	3	55	36	94	0	0	0	0	0	0	14	49	12	75	0	35	6	27	68	237
07:45 AM	1	6	86	28	121	0	1	1	0	2	0	14	55	17	86	0	51	16	34	101	310
08:00 AM	1	2	60	41	104	0	0	1	0	1	0	31	48	11	90	0	48	6	27	81	276
08:15 AM	0	2	67	32	101	0	1	0	0	1	1	28	60	5	94	0	38	5	41	84	280
Total Volume	2	13	268	137	420	0	2	2	0	4	1	87	212	45	345	0	172	33	129	334	1103
% App. Total	0.5	3.1	63.8	32.6		0	50	50	0		0.3	25.2	61.4	13		0	51.5	9.9	38.6		
PHF	.500	.542	.779	.835	.868	.000	.500	.500	.000	.500	.250	.702	.883	.662	.918	.000	.843	.516	.787	.827	.890
Cars+	1	13	263	132	409	0	1	2	0	3	1	82	205	43	331	0	169	33	127	329	1072
% Cars+	50.0	100	98.1	96.4	97.4	0	50.0	100	0	75.0	100	94.3	96.7	95.6	95.9	0	98.3	100	98.4	98.5	97.2
Heavy Vehicles																					
% Heavy Vehicles	50.0	0	1.9	3.6	2.6	0	50.0	0	0	25.0	0	5.7	3.3	4.4	4.1	0	1.7	0	1.6	1.5	2.8




SRF Consulting Group, Inc.

One Carlson Parkway, Suite 150
Plymouth, MN 55447-4443

SRF No. 8060: Hwy 5
Location: Hwy 101/ 78th St
Weekday Count
SRF Consulting

File Name : 130_Hwy 101 & 78th St
Site Code : 09281120
Start Date : 2/13/2013
Page No : 4

Start Time	Hwy 101 Southbound					78th St Westbound					Hwy 101 Northbound					78th St Eastbound					Int. Total
	Peds	Left	Thru	Right	App. Total	Peds	Left	Thru	Right	App. Total	Peds	Left	Thru	Right	App. Total	Peds	Left	Thru	Right	App. Total	
Peak Hour Analysis From 09:00 AM to 12:45 PM - Peak 1 of 1																					
Peak Hour for Entire Intersection Begins at 12:00 PM																					
12:00 PM	0	3	21	28	52	0	14	24	4	42	0	15	33	20	68	0	38	23	5	66	228
12:15 PM	0	2	33	33	68	0	18	13	7	38	0	17	27	23	67	0	37	17	20	74	247
12:30 PM	0	6	29	35	70	0	14	12	2	28	0	16	41	20	77	0	36	26	19	81	256
12:45 PM	0	3	39	33	75	0	17	17	4	38	0	18	28	27	73	0	34	26	12	72	258
Total Volume	0	14	122	129	265	0	63	66	17	146	0	66	129	90	285	0	145	92	56	293	989
% App. Total	0	5.3	46	48.7		0	43.2	45.2	11.6		0	23.2	45.3	31.6		0	49.5	31.4	19.1		
PHF	.000	.583	.782	.921	.883	.000	.875	.688	.607	.869	.000	.917	.787	.833	.925	.000	.954	.885	.700	.904	.958
Cars+	0	14	117	128	259	0	59	66	16	141	0	66	125	89	280	0	141	90	56	287	967
% Cars+	0	100	95.9	99.2	97.7	0	93.7	100	94.1	96.6	0	100	96.9	98.9	98.2	0	97.2	97.8	100	98.0	97.8
Heavy Vehicles																					
% Heavy Vehicles	0	0	4.1	0.8	2.3	0	6.3	0	5.9	3.4	0	0	3.1	1.1	1.8	0	2.8	2.2	0	2.0	2.2



SRF Consulting Group, Inc.

One Carlson Parkway, Suite 150
Plymouth, MN 55447-4443

SRF No. 8060: Hwy 5
Location: Hwy 101/ 78th St
Weekday Count
SRF Consulting

File Name : 130_Hwy 101 & 78th St
Site Code : 09281120
Start Date : 2/13/2013
Page No : 5

Start Time	Hwy 101 Southbound					78th St Westbound					Hwy 101 Northbound					78th St Eastbound					Int. Total
	Peds	Left	Thru	Right	App. Total	Peds	Left	Thru	Right	App. Total	Peds	Left	Thru	Right	App. Total	Peds	Left	Thru	Right	App. Total	
Peak Hour Analysis From 01:00 PM to 04:45 PM - Peak 1 of 1																					
Peak Hour for Entire Intersection Begins at 04:00 PM																					
04:00 PM	0	2	52	53	107	0	20	15	2	37	0	20	65	16	101	0	54	17	13	84	329
04:15 PM	0	3	62	62	127	0	21	14	0	35	0	21	58	21	100	0	68	13	13	94	356
04:30 PM	0	3	61	56	120	0	22	17	7	46	0	27	56	28	111	0	50	10	17	77	354
04:45 PM	0	4	55	62	121	0	20	13	9	42	0	25	68	16	109	0	64	12	13	89	361
Total Volume	0	12	230	233	475	0	83	59	18	160	0	93	247	81	421	0	236	52	56	344	1400
% App. Total	0	2.5	48.4	49.1		0	51.9	36.9	11.2		0	22.1	58.7	19.2		0	68.6	15.1	16.3		
PHF	.000	.750	.927	.940	.935	.000	.943	.868	.500	.870	.000	.861	.908	.723	.948	.000	.868	.765	.824	.915	.970
Cars+	0	12	228	233	473	0	83	59	18	160	0	92	246	80	418	0	235	52	56	343	1394
% Cars+	0	100	99.1	100	99.6	0	100	100	100	100	0	98.9	99.6	98.8	99.3	0	99.6	100	100	99.7	99.6
Heavy Vehicles																					
% Heavy Vehicles	0	0	0.9	0	0.4	0	0	0	0	0	0	1.1	0.4	1.2	0.7	0	0.4	0	0	0.3	0.4

